

BP® quality. Even after many washes.

We provide you with care instructions on each and every product on the sew-in label.

The right care

Washing



Normal washing programme



Normal washing programme



Normal washing programme



Gentle cycle

Ironing



Do not hot iron
Caution when ironing with steam (110 °C)



Moderately hot iron (150 °C)



Hot iron (200 °C)

Bleaching



Do not chlorinate



Bleaching allowed

Drying



Do not tumble dry



Tumble dry, gentle programme (60 °C)



Tumble dry, normal programme (80 °C)

Cleaning



Do not dry clean
Do not wet clean



Professional normal dry clean



Professional delicate dry clean

The majority of the BP® products carry the **PRO label**. The PRO label indicates that the product meets the requirements of ISO 30023. Tests have been conducted for suitability for industrial laundering in accordance with ISO 15797, namely using washing programmes (1-8), in the tunnel finisher and/or tumble dryer. However, the PRO label does not provide any specific care instructions. Real-life test washes in an industrial laundry should be carried out before using any BP® product.

PRO label (example)



- Washed with programme no. 8 as specified in ISO 15797
- Then dried in the tumble dryer or tunnel finisher and tested

Drying symbols




Drying in the tumble dryer



Drying in the tunnel finisher/cabinet finisher

Washing symbols



1, 2 White work clothing and/or coloured trim, peracetic acid bleach



3, 4 White work clothing, chlorine bleach



5, 6 White work clothing and/or coloured trim, hydrogen peroxide



7, 8 coloured work clothing

Some of our products **do not carry the PRO label**. Nevertheless, they may be washed in an industrial laundry in certain circumstances. Extensive test washes should be carried out on these products especially, to ensure the correct care procedures are used. We classify our products' appropriateness for industrial laundering as follows:



Low level of appropriateness for industrial laundering:
≤ 40 °C, air drying



Medium level of appropriateness for industrial laundering:
≤ 60 °C, lower drying temperature



High level of appropriateness for industrial laundering:
≤ 5 °C, tumble/tunnel finisher drying

Successful cleaning and the wear and tear on clothing are determined by the following four basic parameters: chemistry, mechanics, temperature, time (Sinner's Circle). To keep things simple, the classification on the left only considers the washing and drying temperature. The other factors should naturally also be taken into account when carrying out real-life test washes.